



*These Displays are to be used with Sylvac Probes no hand tool input. See Sylvac Probes page 118 for Specifications.*

## Sylvac Digital Indication Units for Sylvac Probes

### D-50S Pro



- Digital display with 2 probe inputs
- Data output RS232C
- Power supply by AC adapter
- Light and compact
- Extreme ease of use
- Linear error correction

Part Number	Description
54-618-142	Digital Indication Unit (D-50S Pro)
54-618-166	Data Cable RS232C 9m/9m 9 Pin 2m

### D-50S



- Relative and Absolute measurement
- Digital Resolution:
  - Inch: .0001" Metric: .001mm
  - Inch: .00001" Metric: .0001mm
- 2 probe inputs
- Reversible measuring direction
- Direct inch/metric conversion
- RS232 duplex with command structure
- Programmable preset
- Lockable function keys
- Foot pedal connection
- Built-in calibration sequence

***D-50S Pro has all the features of the D-50S and also includes linear error correction.***

Part Number	Description
54-618-148	Digital Indication Unit (D-50S), Includes foot pedal
54-618-166	Data Cable RS232C 9m/9m 9 Pin 2m

